



ULTRA VIOLET

Cause	Problem	Action	
<ul style="list-style-type: none">1. INNER END CAPS LOOSE2. O RINGS NOT GREASED3. INCORRECT ASSEMBLY4. O RINGS DAMAGED5. QUARTZ TUBE CRACKED	WATER LEAKS	<ul style="list-style-type: none">1. TIGHTEN 1/4 TURN2. GREASE3. RE ASSEMBLE4. REPLACE5. REPLACE	OK
<ul style="list-style-type: none">1. NO FAN FITTED2. FAN FAILURE3. ELECTRICAL PROBLEM4. WRONG UV TUBE FITTED	HIGH CONTROL UNIT TEMP	<ul style="list-style-type: none">1. INSTALL FAN UNIT2. REPLACE FAN3. REPAIR4. REPLACE	OK
<ul style="list-style-type: none">1. HOUR RESET WIRE CONNECTED2. FAULTY METER	HOUR METER NOT INCREMENTING	<ul style="list-style-type: none">1. DISCONNECT2. REPLACE	OK
<ul style="list-style-type: none">1. TUBE FAULT2. STARTER FAULT3. BALLAST FAULT4. CONNECTION FAULT	UV TUBE DOES NOT START	<ul style="list-style-type: none">1. REPLACE2. REPLACE3. REPLACE4. REPAIR	OK

Topline Electronics Ltd
Unit A8 Ropemaker Park
Diplocks Way Ind Estate
Hailsham East Sussex
BN27 3GU
Tel 01323-440760
Fax 01323-844508
E Mail Info@topline.uk.net
www.topline.uk.net